









Parts List

			
RA-01 Clamp	x1 Gasket	x1 M6 x 12mm bolt	x2 M6 Spring washer

Tools Required

	
4mm Allen key x1	Power Drill
	
Hole Saw Max ø20mm (25/32")	



Share your installation with us.



UK & International
+44 (0)1392 531280
sales@scanstrut.com

For further installation
and warranty information
please visit:
www.scanstrut.com

USA
+1 860 308 1416
usasales@scanstrut.com

